APPENDIX 4


Health And Safety Information (Used During Construction)					
In addition to the hazards normally associated with the types of work detailed on this drawing, please note the following :					
Construction Phase					
Residual risk that may not be obvious to a 'competent contractor':	Action required to control the residual risk:				
 Live Ferry Service Maintained/Operational During Works 	It is anticipated that these works will take place in an operational ferry terminal, therefore works shall be timed such that they avoid clashes with ferry sailings.				

IT IS ASSUMED THAT ALL WORKS WILL BE CARRIED OUT BY A COMPETENT PERSON WORKING TO AN APPROVED SAFE SYSTEM OF WORK

Pier Structure

© Mott MacDonald

This document is issued for the party which commissioned it and for specific purposes connected with the captioned project only. It should not be relied upon by any other party or used for any other purpose. We accept no responsibility for the consequences of this document being relied upon by any other party, or being used for any other purpose, or containing any error or omission which is due to an error or omission in data supplied to us by other parties.



State of Lot of

BOREHOLES (PLANNED)

NAME	TOTAL DESIGN DEPTH (m)	EASTINGS		
BH101	13	422561.8766		
BH102	13	422558.7812		
BH103	9	422458.8176		
BH104	9	422516.7115		
BH105	9	422490.4343		
BH106	9	422466.6361		
BH107	9	422545.5099		
BH108	9	422520.0349		
States of the local division in which the local division in the lo				

Quayside

Ferry Berth

	VIBRACORES (PLANNED					
NAME	TOTAL DESIGN DEPTH (m)	EASTINGS				
VC101	1	422457.7968	1			
VC102	1	422517.4129	1			
VC103	1	422487.8252	1			
VC104	1	422463.4651	1			

1

1

422538.2727

422517.0359

VC105

VC106

BH102

© 2021 Microsoft Corporation © 2021 Maxar ©CNES (2021) Distribution Airbus DS

"Noust" vessel storage area

0 25m 1:500

	 All dimensions All contours Chart Daturn Tide levels MHWS: + MHWN: + MLWN: + Access for shall not be https://www The Contra 	e disrupted by the Contra v.fairisle.org.uk/travel.htr	s otherwise noted. hart Datum (mCD). hoe Datum (Lerwick) /s: nall be maintained at all times. actor. Ferry information is avai ml e for maintaining the seabed fi	ilable at
NORTHINGS 1072465.4356 1072495.9506 1072557.1334 1072567.1618 1072586.9293				
1072595.4658				
1072606.1533	Key to symbols			
	Reference drawi	Vibration Core Locati ings 0-GI-DR-C-0002	ons Grutness Ground	d Investigation
NORTHINGS				
1072552.0816	P01 12/10/21	LM For Informa	ation	CO MR
1072563.8008	Rev Date	Drawn Description	1	Ch'k'd App'd
1072582.9435 1072590.8217 1072608.4199 1072608.8768	M MOTT MACDONA		St Vincent Plaza 319 St Vincent Street Glasgow, G2 5LD United Kingdom T +44 (0)141 222 45 F +44 (0)141 221 20 W mottmac.com	00
	8 No Lerv She	tland Islands orth Ness Bu vick tland 0LZ	s Council usiness Park	
		Isle and Greestigation	utness Ground	

Investigation Fair Isle Exploratory Hole Location Plan

Designed	rawn L Marini		DD	Eng check C OI		hl	со	
Drawn			LM	Coordination	dination C Ohl		CO	
Dwg check			со	Approved	MR	M Ross		
Scale at A1	Scale at A1			Rev		Security		
1:50	1:500		PRE		P01		STD	
Drawing Number								
418429-MMD-00-GI-DR-C-0001								

50m