


Corner	(Latitude)	(Longitude)
1	56.045742	-3.596513
2	56.045724	-3.596496
3	56.045723	-3.596576
4	56.045732	-3.596577

Corner	Degrees. minutes (Latitude)	Degrees. minutes (Longitude)
1	56° 2.744520'	-3° 35.790780'
2	56° 2.743440'	-3° 35.789760'
3	56° 2.743380'	-3° 35.794560'
4	56° 2.743920'	-3° 35.794620'



Black = Scope of Works

RED = Area of Sea wall repair

STATUS: PURPOSE OF ISSUE:
FOR INFORMATION

CLIENT:
SPGAL

PROJECT:
SEA_WALL_REPAIR
VALLEYFIELD_ASH_LAGOONS

DRAWING NUMBER:
C21252_001 Seawall Repair

SCALE: A1	FIRST ISSUE DATE: 16/02/22	REV: 1
--------------	-------------------------------	-----------



CIVIL ENGINEERING ■ ENERGY ■ DEVELOPMENT ■ PLANT ■ FARMING & ESTATES

Reproduced from the Ordnance Survey Map with the permission of Her Majesty's Stationery Office, Crown Copyright Licence Number 100030887
Contains Ordnance Survey data © Crown copyright and database right 2017