

Troqueer WwTW Bank Work Area Drone Photos 30th June 2025

Photo 1 (below): Existing WwTW Outfall works area



Photo 2 (below): Embankment work area looking downstream



Photo 3 (below): embankment work area viewing upstream



Photo 4 (below): Failing embankment adjacent to southern (downstream) end of WwTW



Photo 5 (below): Downstream work extent. Photo viewing downstream.

