

MSD101000 Wemyss Bay



Photograph 14 - Section 3 - 9M 1328Y - Undermining at toe - 18.06.23



Photograph 15 - Section 3 - 9M 1344Y - Undermining at toe - 18.06.23



Photograph 16 - Section 3 - 9M 1359Y - Undermining at toe, majority of void filled shingle - 18.06.23



Photograph 17 - Section 3 - 9M 1395Y - Voids at toe of concrete repair no change (750mm) - 18.06.23



Photograph 18- Section 3M- 9M 1400Y- repair condition, void at toe of wall- 18.06.23



Photograph 20 - Section 3 - 9M 1400Y to 1412Y - Undermining at toe slight det - 18.06.23



Photograph 21 - Section 3 - 9M 1411Y - mass concrete repair- 18.06.23



Photograph 22 - Section 3 - 9M 1414Y -void @ repair 750 deep- 18.06.23



Photograph 23 - Section 3 - 9M 1416Y - Small void in concrete repair at toe 500mm deep- 18.06.23