

CLIMAVORE

NAVIGATIONAL RISK ASSESSMENT

Site Name or Description of Operation: CLIMAVORE CLIP / Uig

Site/Operation Location(s): Uig Bay, Isle of Skye

Site Manager: Shona Cameron

Main Risk/Hazard	Reason's cause/Effect	Probability: High 3 Medium 2 Low 1	Mitigation	Rating after mitigation	Owner of risk
Contact - farm structure by fishing boat or pleasure craft/kayak etc	A boat not being aware of the site of farm during high tide when submerged. Could cause damage to boat and farm structure	Medium	Marking farm structure with yellow buoys at the corner of each site. Signage on pier to notify users of siting of farm. Building community awareness of structure. Siting of farm away from main harbour. Regular checking of site to ensure buoys are still in position	Low	Site manager
Breakage of farm structure away from site	If farm structure was to break or be damaged and drift from marked site, a passing boat could encounter it and cause damage.	Medium	Farm structure will be maintained on a regular basis to ensure any weak points are identified before damage occurs. This will be undertaken more often when storms are forecast. The structures will be installed by a professional to make sure they are less likely to be damaged.	Low	Site manager/ site engineer