



Photo 1 – View along quay at proposed pontoon location



Photo 2 – General view of quay at proposed pontoon location



Photo 3 – General view of proposed pontoon location



Photo 4 – General view of quay wall showing typical concrete defects and ladder to be removed



Photo 5 – General view of quay wall showing typical concrete defects



Photo 6 – General view of quay wall showing typical concrete defects



Photo 7 – Proposed location of new ladder recess and ladder