


Site Pictures MSC6281 Moonzie Burn

Sketch 1

Site layout - ECN2 090/165



Overview of works location



General view of works location



Example of cracks



Cracks within structure



Cracks within structure



Return fracture