



SUBMARINE CABLES
 Mariners are advised to be aware of the presence of submarine cables in the vicinity of pipelines. Pipelines and their presence may not be shown on the charted depth. Seabed undulations may cause a vessel to become irrecoverably stuck in severe danger.

ANCHORAGE
 Within the area indicated, vessels are advised to anchor in the positions outside the zone.

HIGH SPEED CRAFT
 High speed craft operators are advised to maintain a safe speed.

HISTORIC SITES
 The sites of historic interest are shown. Vessels are advised not to anchor in these areas without the permission of the appropriate authorities.

VESSEL SERVICES
 For details of the services and vessel requirements, refer to the Admiralty List of Buoyages.