

Coastal Defences between Silver Sands Beach and Burntisland

Proposed areas of licensable activity & indicative photographs of areas of defects for repair (not exhaustive)

CD 200/564 and CD 200/494 - NT20128559 to NT 22207 86064

Erosion of revetment toe, and vegetation growth at crest of revetment.



Washout and voiding near existing collapse with rip-rap repair.



Erosion and washout of masonry and bagwork revetment face.



Erosion of revetment face and loss of existing bagwork repair.

Erosion and undercutting of steep bagwork buttress.



Large areas of washout, including erosion of previous bagwork repair.



Loss of pointing across revetment face, loss of individual stones. Similar defects encountered on Sections 1, 3 and 5.



Erosion and undercutting of exposed soil slope beyond end of revetment.



Erosion of soil slope.