

Figures



Figure 1: Coastal Processes at site, on annotated aerial photograph of Gourock




Figure 2: Cross-sections of the site, extracted from topographic survey



Photo 1: Proposed Development Site, looking to the east from Kempock Street car park



Photo 2: Beach sediment on western side of site (note the barnacle cover)



Photo 3: Rocks fronting the old concrete blocks along the western side of the site



Photo 4: Short section of shingle beach at the eastern side of the site



Photo 5: Finer shingle sediment on the lower part of the shingle beach at the eastern side of the site.