

13.04.2023

Client: Gillian Conway

SUBJECT: Seabed Survey

LOCATION: Loch Crearan – N 56`32.521 W 005`23.666

On behalf of KMASS Marine Ltd we can confirm that on the 13.04.2023 we conducted a seabed survey on behalf of our client Gillian Conway who is proposing to install a mooring at this location

Our findings are a mixture of clay mud and shale seabed at a water depth of 6 meters approximate.

All Kmass marine divers have been fully briefed and shown pictures of the invasive species *Didemnum vexillum* ,carpet Sea- Squirt..

We can confirm that on the 13.04.2023 we found no Invasive species in this area. Kmass procedure on finding *Didemnum vexillum* we would be to take a digital photo to document our findings, we would also notify (SEARS) of the approximate location.

If you require any further information, please do not hesitate to contact me on <Redacted> or <Redacted>

Yours sincerely,

Kevin Healey
Director of KMASS Marine Ltd

(B) Distribution of serpulid reefs and horse mussel beds and areas where dive survey is required

