



# Kelton Septic Tank – Second SI Visit

---

SI WORKS 7-10<sup>th</sup> January





Septic Tank – before and after, inclusive of access chamber that was buried.




Camera from  
chamber to  
outfall –  
inspection.

---








Area where the pipe was assumed to be collapsed before excavation, ground is saturated and full of sewage. This is where the pipework ends and runs off to the river.

---







## Trial Digs to locate outfall pipe

---





# Trial Digs to locate outfall pipe

---








## Trial Digs to locate outfall pipe

---







## Trial Digs to locate outfall pipe

---







## Trial Digs to locate outfall pipe

---







Reinstatement photos

---



\_\_\_\_\_

