

# Project Overview

The most recent survey of the SHEFA cable shows that the cable has been rubbing against the rock of the seabed causing lost of the cable protecting cover.

