

Stirling Old Bridge



Stirling Old Bridge




Image 1:
Boundary of the activities
described in the application

Stirling Old Bridge



Image 2:
Stirling Old Bridge looking
Upstream from North Bank

Stirling Old Bridge



Image 3:
Pier 3 (eastern) showing
typical rock armour work

Stirling Old Bridge



Image 4:
East Pier showing typical loss
of rock units from armour fill