

CULLIPOOL COASTAL PROTECTION

SITE PHOTOGRAPHS



Plate 1 – Cullipool Beach 1976, note depth and grade of beach materials

© HES. Reproduced courtesy of J R Hume



Plate 2 – Cullipool Beach 2023, significant scouring



Plates 3 and 4 – damage to sea wall and wash out of made ground, 2022



Plate 5 – sea wall with larger boulder rip rap 2023